

# DIVISION OF OIL, GAS AND MINING

1594 West North Temple, Suite 1210 PO Box 145801

Salt Lake City, Utah 84114-5801

Kathleen Clarke **Executive Director** Lowell P. Braxton

Michael O. Leavitt

Governor

801-538-5340 801-359-3940 (Fax) Division Director 801-538-7223 (TDD)



# INSPECTION REPORT

Partial <u>X</u>	XXX Complete	_Exploration
Inspection Date:	07/22/2002 Time:	12:00pm-3:00pm
1	Date of Last Inspec	

Mine Name: <u>Emery Deep Mine</u> County: <u>Emery</u> Permit Number: <u>C/015/015</u>						
Permittee and/or Operator's Name: Consolidation Coal Company						
Business Address: P.O. Box 566, Sesser IL 62884/P.O. Box 527, Emery, Utah 84522						
Company Official(s): Seth McCourt						
State Official(s): Stephen J. Demczak Federal Official(s): None						
Weather Conditions: Warm, 90's, Sunny						
Type of Mining Activity: Underground XXX Surface Prep Plant Other						
Existing Acreage: Permitted 5180 Disturbed 247 Regraded Seeded Seeded						
Status: Active						

# REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
  - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		<b>EVALUATED</b>	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]		[X]	
2.	SIGNS AND MARKERS	$\Box$	ĹĴ		$\Box$
3.	TOPSOIL	[ <u>X</u> ]		[X]	$\Box$
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[X]		[X]	
b.	SEDIMENT PONDS AND IMPOUNDMENTS	[X]	$\Box$	[X]	
c.	OTHER SEDIMENT CONTROL MEASURES	$\Box$			
d.	WATER MONITORING	[X]	$\Box$	[X]	$\Box$
e.	EFFLUENT LIMITATIONS			$\Box$	
5.	EXPLOSIVES	[X]		[X]	$\Box$
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES				
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[X]		[X]	
8.	NONCOAL WASTE	[X]		[X]	
9.	PROTECTION OF FISH, WILDLIFE AND RELATED				
	ENVIRONMENTAL ISSUES		$\Box$	$\Box$	
10.	SLIDES AND OTHER DAMAGE				
11.	CONTEMPORANEOUS RECLAMATION		$\Box$		
12.	BACKFILLING AND GRADING			$\Box$	
13.	REVEGETATION				$\Box$
14.	SUBSIDENCE CONTROL		$\Box$		$\Box$
15.	CESSATION OF OPERATIONS	. []		$\Box$	$\Box$
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING		$\Box$		
b.	DRAINAGE CONTROLS		$\Box$		$\Box$
17.	OTHER TRANSPORTATION FACILITIES		$\Box$	$\Box$	
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[X]		[X]	
19.	AVS CHECK (4 <sup>th</sup> Quarter- April, May, June)		$\Box$		
20.	AIR QUALITY PERMIT			$\Box$	
21.	BONDING & INSURANCE	$\Box$	$\Box$		

## INSPECTION REPORT

(Continuation Sheet)

PERMIT NUMBER: <u>C/015/015</u>

DATE OF INSPECTION: 07/22/2002

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

# 1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The permittee has two permitting actions with the Division. These are the modification to the 4<sup>th</sup> East Portals Facility and the installation of the power line to the 4<sup>th</sup> East facilities. Both amendments have been reviewed and have deficiencies.

## 3. TOPSOIL

The 4<sup>th</sup> East topsoil pile has been seeded and mulched. The topsoil pile will be watered in the near future with sprinkler system.

# 4A. HYDROLOGIC BALANCE: DIVERSIONS

The diversions were spot-checked throughout the property and complied with the performance standards.

# 4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The sediment ponds were inspected with no hazardous conditions noticed.

### 4D. HYDROLOGIC BALANCE: WATER MONITORING

The permittee was informed that the Division would not accept "No access" to a water-monitoring site as a way of complying with the requirements of the R645 Coal Rules and the MRP.

### 5. EXPLOSIVES

The blasting reports were inspected and complied with the R645 Coal Rules.

# 7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

The refuse pile was inspected with no hazardous conditions noticed.

### 8. NONCOAL WASTE

The disturbed area was clear of non-coal waste.

## 18. SUPPORT FACILITIES/UTILITY INSTALLATIONS

The permittee is continuing to develop the 4<sup>th</sup> east portals. All drainage controls are in place.

Inspector's Signature:

Stephen J. Demczak #39

Date: August 1, 2002

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM

Tim Kirschbaum, Consol, Illinois

Steve Behling, Consol, Emery

Price Field office

O:\015015.EME\Compliance\2002\p\_0722.doc